

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

OGM

Representatives Present During the Inspection:					
OGM	Priscilla Burton Environmental Scientist III				
OGM	Ingrid Wieser Environmental Scientist II				
OGM	James Owen				
OGM	Pete Hess Environmental Scientist III				

Steve Christensen Environmental Scientist II

**Inspection Report** 

Permit Number:	C0070001			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, June 09, 2010			
Start Date/Time:	6/9/2010 2:00:00 PM			
End Date/Time:	6/9/2010 3:30:00 PM			
Last Inspection:	Wednesday, May 26, 2010			

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 60 F

InspectionID Report Number: 2387

Accepted by: jhelfric

6/21/2010

Permitee: LODESTAR ENERGY INC

Operator: WILLIAM BISHOP, TRUSTEE

Site: WHITE OAK MINE

Address: 2525 HARRODSBURG RD STE 235, LEXINGTON KY 40504-1628

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

**Current Acreages** 

<b>Total Permitted</b>	3,906.00
Total Disturbed	151.10
Phase I	
Phase II	
Phase III	

Mineral Ownership

Other

✓ Federal✓ State✓ County✓ Fee

Types of Operations

✓ Underground✓ Surface✓ Loadout

☐ Processing☐ Reprocessing

Date

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Accompanied members of the reclamation team to the site to measure drainage width and depth. Took soil samples.

Inspector's Signature

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utah!

Thursday, June 10, 2010

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 09, 2010

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	<b>V</b>		~	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	✓		<b>✓</b>	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 09, 2010

Page 3 of 3

## 3. Topsoil

Composite samples of topsoil taken from the east and west side of the channel at the point of steepest grade. Soil was air dried and will be taken to the BYU soil laboratory for analysis.

## 13. Revegetation

Vegetation is still sparse but better established on some areas including the North facing slope and areas near undisturbed vegetation. Species present on reclaimed areas include yarrow, penstamon, sagebrush, woods rose, coneflower, blue aster, and fescue. A full vegetation survey will be conducted later this summer.